Date:

Tuesday, 19/08/2008 4:07:23 PM

Julie Lecocq

Process Sheet

MAR

Customer

: CU-DAR001 Dart Helicopters Services

Job Number

Drawing Name

: 90 DEGREE COVER PLATE

: 41511-2

Estimate Number

: 13405

P.O. Number

This Issue

: 19/08/2008

S.O. No. :

Part Number

: PB674300169

Prsht Rev. First Issue

: NC

Drawing Number

: B6743001 PAGE25

: //

Project Number

: N/A

Previous Run

Type

Drawing Revision

B1

: 40069

Material

Written By

Due Date : 18/09/2008

Checked & Approved By Comment

: Est Rev:A

08-06-20 new issue DD verified by:ec

: SMALL /MED FAB

Additional Product

Job Number:



Description:

Seq. #: 1.0

Machine Or Operation: M6061T6S032

6061-T6 Sheet 0.032"




Comment: Qty.:

1.4234 sf(s)/Unit

42.7014 sf(s) Total:

6061-T6 Sheet 0.032" WATER JET





Comment: FLOW WATER JET

1-Cut as per Dwg B67-43001

Dwg Rev:__ Prog Rev:_

R 8-9-8

****grain direction along 9.144" ****

2-Deburr if necessary

3.0

2.0

QC2

INSPECT PARTS AS THEY COME OFF MACHINE



FB 8-9-8 Comment: INSPECT PARTS AS THEY COME OFF MACHINE

4.0

QC8

SECOND CHECK



counter

Comment: SECOND CHECK

5.0

BRAKE NO

NC BRAKE

Comment: NC BRAKE

Bend as per Dwg B67-43001



Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES								
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
<u> </u>										

Part No: 1867-43001-69	PAR #:09-011 Fault Category: Zns /Design	NCR: SNo	DQA:	Date: (5/02/17)
Resolution:	Disposition:			Date: OS/W/13

NCR: 41	511-2	. W	ORK OR	DER NON-CONFORMANC	E (NCR)			
DATE	STEP	Decementary of NO		Corrective Action Section B	Verification	Approval	Approval	
			Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector
		PART WILL NOT FIT .		SCRAP & DESTROY QT1.10	SAD			
09-0211	5.0	UPON ASSY (REF B45076)		EUG. TO ISSUE NEW DWG.	09-02-12	. / /	h	
		10 PARTS. R.C. PART REQUIRED REDESIGN.	90211	EUG. TO ISSUE NEW DWG.		16-012	cyora	ogloalu
				`				
					·			
	1							

NOTE: Date & initial all entries

Process Sheet

Drawing Name: 90 DEGREE COVER PLATE Customer: CU-DAR001 Dart Helicopters Services **Part Number: PB674300169** Job Number: 41511 Job Number: Seq. #: **Machine Or Operation: Description:** 6.0 QC5 INSPECT WORK TO CURRENT STEP Comment: INSPEC WORK TO CURRENT STEP 7.0 LARGE FAB 1 LARGE FABRICATION RESOURCE 1 **Comment: LARGE FABRICATION RESOURCE 1** Weld assembly as per dwg B67-43001 SMALL FAB 1 8.0 SMALL & MEDIUM FAB RESOURCE 1 Comment: SMALL & MEDIUM FAB RESOURCE 1 1- grind weld flush 9.0 QC10 VISUAL INSPECTION OF GROUND WELDS Comment: VISUAL INSPECTION OF GROUND WELDS 10.0 QC5 INSPECT WORK TO CURRENT STEP Comment: INSPECT WORK TO CURRENT STEP 11.0 HAND FINISHING HAND FINISHING RESOURCE #1 Comment: HAND FINISHING RESOURCE #1 Chemical Conversion Coat as per QSI 005 4.1 POWDER COATING 12.0 POWDER COATING Comment: POWDER COATING Powder Coat Green Sandtex (Ref. 4.3.5.8) as per QSI 005 4.3 START TIME: **OVEN TEMPERATURE:** FINISH TIME: 13.0 QC3 INSPECT POWDER COAT/CHEMICAL CONVERSION Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION

Tuesday, 19/08/2008 4:07:23 PM Julie Lecocq

Process Sheet

Sustomer: CU-DAR001 Dart Helicopters Services

Drawing Name: 90 DEGREE COVER PLATE

Job Number: 41511

Part Number: PB674300169

Job Number:



Seq. #:

Machine Or Operation:

Description:

PURCHASING

Comment: PURCHASING

SEND TO TALMAR FOR FOAM AND FABRIC

15.0

14.0

PACKAGING 1

PACKAGING RESOURCE #1

Comment: PACKAGING RESOURCE #1

Receive & Inspect For Transit Damage

16.0

QC6

DIMENSIONAL CHECK



Comment: DIMENSIONAL CHECK

17.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify and Stock

Location:

18.0

QC21

FINAL INSPECTION/W/O RELEASE



Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



Mf 09-02-11

. ė		SPACE		• .	40			1	Work Order:	41511
Descripti	on:	90	COVER	- PL	ATF	æ _{jt}	· · · ·	 	Part Number:	
nspectio	n Dw	g:	, Re						rait Number:	PR 67430
PB	674	3001-69	, ,,	n: BI		· · · · · · · · · · · · · · · · · · ·				Page 1 c
		.: •		T ARTI	CIFI	Nebeci			CKLIST	
		•	Γ	~		NOPEC				•
Drawin				X Fire	st Arti	cle	X	Proto	type	
	•	Tol	erance	Ac	tual				Method of	
Dimensi	on	<u> </u>		Dime	nsion	Accept	t F	Rejest	Inspection	Comment
lo	6	7.	630	1.0	500		+	<u>3 t</u> y		<u> </u>
2.5	\circ	he/	υ } Ο		569		+			
4.	7	- /	030			82	+-	-		
19	75	4	030		<u>Ma</u>	×				
	-		U 30	17.	35	×	1_		•	
			<u> </u>						*.5	
				+			1			
		···		·						
				ļ						·
	-+							,		
	\dashv									
· · · · · · · · · · · · · · · · · · ·			-							······································
					-					· · · · · · · · · · · · · · · · · · ·
					-					
	\bot	•								
								 -		
	T						<u>:</u>			
					<u> </u>					
	1								_	
										
										·
<u> </u>	+									
			·	- i						
				. 4						
red by:		·	7							
	R.		Aud	ited by:	5	, ,		Prototy	pe Approval:	
Date:	<u>&-</u>	9-8		Date:	08/1	09/09				1/
Date	Cha	nge				4-1			Date:	.17
	New	Issue	<u>-</u>		·				Revised by	Approved

